




# Willy Nillie's P-51 Fuselage





Machine gun wing pieces




Servo Tray reinforcement



Fuselage Pieces and placement




Motor Mount and wing reinforcement pieces



Wing bolt fuselage piece



Place other side of fuselage on




Place Reinforcement brace





Lower air vent assembly. Glued to wing for bolt assembly



Hatch Assembly



Front Assembly



Stringer Placement